



8 Technical Data

## **Housing Dimesions:**









	GPT-4352-V.24	GPT-4352-TTI						
Print technique	Fixed thermal print line							
Paper / printing width	57.5 ± 0.5 mm / 48 mm							
Resolution	8 dots / mm ,	8 dots / mm , 384 dots / line						
Print Speed	up to 50	) mm/s						
Voltage supply	(3.0) 3.5 - 7.2 V	4.5 - 7.2 V						
	Optional: charging circuit for one Li-lor	n cell (3.6V) ,or for 3,4 , or 5 NiMH cells						
Current max. sleep mode	app. 0 µA or 1	50μA /infrared						
Current max. idle:	app. 3 mA depend	ling on components						
Current max. printing app		. 0.7 A - 6 A at 5 V						
	RS232 up to 57.6 kbps	ΠI						
Interfaces	Optional: Infrared on board or with exter-							
	nal adapter	preparation), throughTTL: RS422/485, TTY						
	Baud rates:1,200; 2,400; 4,800; ,600; 19,200; 38,400; 57,600							
Interfaces	Mode: adjustable: 7.8 data bits, 1.2 stop bit , none, odd, even parity							
	Handshake:hardware handshake and XON / XOFF							
Data Compression	Factor app. 3:1 (for graphic commands); PC-compatible; Windows driver							
Characters, cpl	24, 32, 42, and 54							
Bar Code	Code39, 2 out of 5 int, EAN13, EAN 8							
	0 °C to 50 °C ( -10 °C to +6	60 °C with GeBE HQpaper)						
Environment	10% to 80% rel. humidity, no moisture condensation							
MTBF	50 km printed paper							
Dimensions in mm	76.8 mm x 77.4 mm x 39.3 mm / installation depth: 27 mm							
Roll Diameter	max. 31 mm							
Weight	150 g incl. paper roll							
Housing Material	ABS							
Norms	CE: see conformity declaration							

#### GeBE Elektronik und Feinwerktechnik GmbH

Beethovenstr 15 • D-82110 Germering near Munich • Germany

Phone ++49 (089) 89 41 41-0 • Fax: ++49 (089) 84 021 68 • Email: sales.ef@gebe.net

# **Protocol Printer**



**GPT-4352** 



Module und Geräte zum Eingeben, Auswerten, Anzeigen und Ausdrucken analoger und digitaler Daten.



GeBE Document No.:
SMAN-E-413

# **Operating Manual**

Installation, Safety Instructions

Connecting the Printer

Operation

**Error Detection** 

**Product List and Accessories** 

Technical Data

GeBE Elektronik und Feinwerktechnik GmbH

Beethovenstr 15 • **D-82110 Germering** near Munichn • Germany

Phone ++49 (089) 89 41 41-0 • Fax: ++49 (089) 84 021 68 • Email: sales.ef@gebe.net


GeBE-Doc.-or.: 413-SMAN-E-4352-V1.0

#### **Installation in a Front Panel**

The housing of the GPT-4352 printer can be installed with two screws in a cut-out that is easy to make. The contact surface is flat. The edge of the housing juts out, covering the space between panel and housing.

The housing is pushed from the outside into the cut-out, and then easily screwed to two fish-plates in the cut-out..


Two holes of 2.8 mm diameter allow the use of M 2.5 screws.



#### Partial installation in a plastic casing

As shown in the picture, the printer housing can also be installed at the edge of the device casing. This installation variant has the part of the printer housing that contains the paper roll extending beyond the unit casing. This saves room in the device casing.

Since the shapes of casings will vary, the design provides no additional cover for installation underneath the bearing edge. Therefore, a clean cut-out on the side of the casing needs to be made in accordance with the unit design. The outer wall of the paper storage can be used up to the slanting slot for the fish-plate, allowing the housing to project about 17 mm, or including the edge, approx. 19 mm.



#### Safety Information:



Read operating manual carefully before operation.

During installation: Always disconnect the power.

Usage in accordance with the operation manual is required for product warranty.

If the user attempts to repair the product, all factory warranties will be null and void.

For technical questions please contact the GeBE Technical Support.

Errors and changes reserved.

The technical data given are non-committal information and do not represent any assurance of certain features.

Our terms of payment and delivery apply. All rights reserved.

### **Product List and Accessories**

Article No.	Controller for ELM-205-LV	Interface					Memory		Batt.		Features				
		RS-232	ТΓ	Infrared (Connector for IR Adapt	Infrared on Board	SPI (for Centronics Adapter)	2 kByte EEPROM	16 kByte EEPROM	Li-Ion Charging Circuit	NiMH Charging Circuit	Power Down	Rewinder	CPL: 24, 42, 54, 32	Color: Anthracite RAL7016	Color: Silk Grey RAL7044
11292	GPT-4352-LV-82-24-V.24-sw	Х									Х		Х	Х	
11335	GPT-4352-LV-82-24-V.24-EVAL-sw	Х					Х			Х	Х	Χ	Х	Х	
11382	GPT-4352-LV-82-24-TTI-EVAL-sw		Х			Х	Х			Х	Х	Χ	Х	Х	
11336	GPT-4352-LV-82-24-IR-EVAL-sw			Х			Х			Χ	Χ	Χ	Х	Х	

## **Options:**

- 16 kByte EEPROM for LOGO download

- 32 kByte EEPROM for LOGO download

- 64 kByte EEPROM for LOGO download

#### **Accessories:**

Interface adapters:

• Centronics : GCT-4382-10 • Infrared : GCT-4382-20

**Mounting Frames** 

• 3HU front für 19" Racks ,18TE width : GMS-4352-3HE-18TE • 96x96 front for DIN housings : GMS-4352-96x96

Paper:

GeBE is offering standard paper rolls with outside coating, 60 g/sq m

Thermal paper standard; 5 years
Thermal paper standard; 15 years
Thermal paper standard; 15 years
Thermal paper standard; 99 years
Thermal paper; two-ply
Thermal paper; adhesive
Thermal paper; low sensibility
GPR-T01-057-031-007-060A on request on request
GPR-T02-057-031-007-100A on request
GPR-Tx1-057-031-007-110A on request
GPR-Tx1-057-031-007-060A on request

Power supply and charging devices:

desk power supply (7V)
 plug-in power supply for 4 Ni-MH cells
 GNG-7V-3A-T
 GNG-6.0V-0,5A-U

**Batteries:** 

• 4 cells Ni-MH 1200 mAh : GNA-4,8-1,2-Ni-MH • 1 cells Li-Ion 800 mAh : GNA-3,6-0,8-Li-Ion

#### Cables:

power supply; 7 wires; 250 mm
 RS232 1:1 SuB-D 9 pin; 1000 mm
 TTI, 5 wires; 500 mm
 charging supply; 250 mm
 SPI-Bus (Centronics); 250 mm
 GKA-414
 GKA-409
 GKA-407

## 6 Error Detection

Not every error is a printer error.

You will save time and money by clearing simple errors yourself.

The following tips are supposed to help you with that:

Following hints might help you:

Symptom	Cause	Remedy
The print seems to print, but	Paper inserted wrong	Insert paper correctly
there is no blackening		
At the start of printing, the		Use a suitable power supply and
LED goes out shortly		short lines. Check all plug-in
The and the angle of the second		connections for trasfer resistances.
The printer only prints a few		Since high peak currents occur
dots in one line.	The power supply is not	with thermal printers, even the
The paper feed works, but	optimal.	smallest transfer resistances result
the self test does not.		in excessive voltage drops. In this
line con tool door not.		case, no power supply would be
The printer only prints a few		strong enough. A bufferingwith
characters in one line.When		capacitors is possible, if the power
I enter more, it won't print at		supply is only slightly too weak,
all.		and large capacitors are used (e.g.
		4,700 μF) .
The print-out is incomplete	The printer buffer is "run	Solution: Check or start using
after a few characters	over" (256 bytes), so data	handshake. (XON/XOFF, or hard-
	are getting lost .	ware). If necessary, lower output
		speed, e.g. go down to 1,200 baud.
		See MAN-D-400, "Interface
		Settings"
The printer prints wrong	RS232 instead of TTL	Use correct interface
characters.	interace or reverse.	Ose correct interface
Characters.	(Characters of the upper	
	area are printed).	
	Wrong baud rate was	Set baud rate through solder
	selected. (A lot of"?" are	bridges or TINIT
	printed)	landges of thirt
	printed,	
	Bad ground connection of	Repair ground connection.
	the printer. If the printer is	
	not grounded right, a part	
	of the printing current will	
	flow through the interface,	
	causing a voltage riseand	
	therefore, a data	
	falsification.	
	Host sends a break signal	Turn off "framing error ". See MAN-
	after print job (printing only "?")	D-400 "Interface Settings"
My Centronics printer works	Printer is electronically not	Measure level of the line that is
with a PC, but not with my	compatiblewith host.	reporting the error. GeBE can
machine.		adjust this.

## **Connecting the Printer**

#### J

#### **During installation:**

#### Always disconnect the power.



#### Connecting the Power Supply:

The printer can be supplied with a fixed voltage from a power supply or from a battery. Battery or power supply are plugged in at the same connector. Through the voltage supply connection, the printer can be supplied with voltages between 3.5 V and 7.2 V. The supply of the logic chip is produced on the board. The power supply cable GKA-406, included in all sets, is connected to connector J4. (3 red wires for + 3.5 -7.2 VDC, 3 black grounding cables, and 1 white cable for a NTC 6.8 KOhm of a NI-MHbattery). The white wire has no function with Li-lon batteries or power supply. We recommend to keep the length of the line as short as possible. A line that is too long can cause bad print quality, or even printer failure.

**Attention:** Avoid confusing the poles of the connections, because it would cause immediate damage to the printer.. Carefully check the connections of the power supply after the wiring is done, before you turn on the power.



**Power Down:** As a standard, the printer is supplied with the power down mode turned off. The power down mode can be activated by removing resistor R37 or jumper J3 (PWDN).

Attention: In the power down mode, the printer will sleep even when the power has been applied.


#### Connecting the Battery Charger:

EVAL printers have a battery charging circuit for one Li-Ion battery (3.6 V), or for 3, 4, or 5 Ni-MH cells.

For the charging, you only need an uncontrolled plug-in power supply GNG-6V-0,5A-U.The charger is connected to the connector J1 and through the cable GKA-409. The maximum charging current depends on the battery voltage (app. 0.7-0.3 A). The charging time for a1200 mA/h battery will be app. 4 - 5 hours. During the charging process, the operation LED will display the charging status. Fast charging and trickle charging will be displayed.

#### **ATTENTION!**

Never use a fixed-voltage power supply for charging the batteries The charging circuit is a "simple - switch" control, meaning that the current limiting is not done in the charging control of the printer, but in the plug-in power supply. Use the suitable GeBE power supply or call us for information.



## Serial Interface:

The interface cable GKA-410 that is included in all sets is connected to the

connector J2. With RS232 versions, this cable can

be connected directly to a PC. A cable with 5 single wires and one open end is available as an option.



#### Parallel Interface:

The printer type GPT-4352-LV-82-TTL-EVAL can be connected to the Centronics interface adapter GCT-4382-10 through the cable GKA-407.



#### Infrared Interface

The printer type GPT-4352-LV-82-IR-EVAL can be connected to the infrared interface adapter GCT-4382-20 through the cable GKA-4xx. Optionally, the IR-tranceiver can also be installed directly on the board.


#### **Serial Interface RS232**

Standard Setting: 9600, n, 8,1

Connector: JST-SH at the printer.

GKA-406: SuB-D 9 pin socket with einer 1:1 assignment to the PC, no 0-modem circuit.

Pin	Signal	Input/ Output	Comment	Assignment GKA-406 D-SUB 9pin
1	GND signal			5
2	TXD		Print data	3
3	RXD	0	Error messages and Xon/Xoff messages	2
	RTS	I	Wake-up / Handshake input of the controller (standard:without function)	
Aus-	+3,0V digital	0	Supply for external adapter	7
über BR5	+3,0 -7,2V Power	0	Supply for external adapter	
5	CTS	0	When the controller can receive data, the level will be logic 0	8



## Status Messages of the Printer:

Messages	Sei Inter		Busy	/Fault	Select	P.End	Status LED on /off; flashing frequency $y := 0$ $y := 1$		Comments	
Faultless				1	1	0	LED on	1:31;0.5 Hz		
operation:										
Reset	"F			0	0	0			Message: < XON R X (or error)>	
Watchdog-reset	"F			0	0	0			After program crashed	
End of error				1	1	0	LED on	1:31;0.5 Hz	Also after reset. When an error is cleared,	
									thecorresponding small letter will be sent,	
									followed by an "X".	
Buffer empty	ΧC	NC							Buffer emptied by 33 characters	
									<dc1> = \$11</dc1>	
Buffer full	ΧO	)FF	1						Buffer has room for 33 more char. <dc3> = \$1</dc3>	
Synchronous	all	le							Processing synchronization commands;	
feedback	Zeic	hen							each character sent	
Errors:		OK		1	1	0				
Paper end	"P"	"p"		1	0		1:1 ;0.5 Hz			
Temp. low	"K"	"k"		0	1	0	1:1 ;0.5 Hz		Temperatur e of print head too low	
Temp. high	"T"	"t"		0	1	0			Temperatur e of print head too high	
Vp too low	"U"	"u"		0	1		1:1 ;0.5 Hz			
Vp too high	"M"	"m"		0	1	0	1:1 ;0.5 Hz	1:1 ;0.5 Hz		
EE-OK	"E0"								EEPROM command completed error-free	
EE-invalid	"E1"								Invalid text file no.	
EE-password	"E2"								Wrong passwort for EEProm access	
EE-overflow	"E3"								Text file memory overflow	
EE-time-out	"E4"								EEPROM byte programming time exceeded.	
Charge battery:										
Fast charging	" "	"L"								
Trickle charging	"f"	"F"					1:7 ; 0.1 Hz	1:7 ; 0.1 Hz	F := charging start f := charging end	

#### Which thermal paper is suitable?

The printer is specified for a paper width of  $57.5 \pm 0.5$  mm, with a weight of 60 g/sq m. GeBE is offering a suitable paper roll as part of the standard program (GPR-T01-057-031-007-060A). Other papers may cause trouble. Thermal papers that are resistent against water, grease, or alcohol are available for special applications. We will gladly assist you in your selection of the suitable thermal paper.

#### Which side of the thermal paper can be printed on?

On the paper roll, the outside is always the side to print on. If you should have any doubts, just do the finger nail test. The thermosensitive side will turn black under the pressure of a sharp object..

#### How do I Insert the Paper?

Use paper rolls with the paper coated on the outside, 57 mm  $\pm$  0.5mm with a winding diameter of 31 mm.

- 1. Unwind about 10 cm (4") of paper from the roll. Keep the layers wound tightly.
- 2. Öpen the printer cover by slightly pressing the lever in the cover up. The print roll gets lifted from the mechanism together with the cover. The cover can now be opened easily.
- 3. Insert the paper roll in the paper *supply*, so the outside shows toward the printer mechanism. Only the outside is printable.
- 4. Close the cover by applying strong pressure. You will be able to hear it snap shut. Now, you can rip off the paper at the tear bar without the cover opening again and the paper sliding back into the printer.

#### The Control Elements of the Printer:

Paper feed button: This button wakes up the printer from the sleep mode and feeds the paper.

**Self test:** Before a connection between printer and host (PC) is established, the function of the printer can be tested by starting a self test. Keep the paper feed button pressed while turning on the power supply. When the feed button is released, the self test will begin. The test will only check the functions of the inner circuit, but not the interface.

Status LED: This LED shows the status of the printer during operation, and - if it is equipped with a charging circuit and a battery - the charging status of the battery during the charging process. See "Messages of the Printer".







